

GOVERNMENT OF TELANGANA
ABSTRACT

Minor Irrigation - "Mission Kakatiya" - Comprehensive restoration of Minor Irrigation Tanks - Administrative approval for Rs. 2289.71 lakhs- Accorded - Orders - Issued.

.....

IRRIGATION & CAD (MI.T) DEPARTMENT

G.O.Ms.No.27

Dated: 12-02-2015.
Read the following:-

1. From the Chief Engineer, Minor Irrigation (GB), Hyderabad, Lr.No.DCE-II/OT2/ Mission Kakatiya/GB/2014-IV, dt.29.12.2014.
2. Govt. Memo No.5845/MIT/A2/2014, Dated:12-02-2015.

-o0o-

ORDER:-

Government of Telangana is launching restoration of all Minor Irrigation Tanks in the State of their original capacity and to effectively utilize the 265.00 TMC of water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of "MISSION KAKATIYA".

2. In the reference read above, the Chief Engineer, Minor Irrigation(GB) has submitted proposals under "Mission Kakatiya" for comprehensive restoration of tanks for according administrative approval and as per the statement below:

Sl.No.	District	No. of Tanks	Ayacut (Acres)	Cost Estimates (Lakhs)	Remarks
1.	Karimnagar	27	2633	726.99	Annexure-I
2.	Adilabad	22	1886	388.65	Annexure -II
3.	Warangal	23	2020	845.97	Annexure-III
4.	Khammam	12	738	328.10	Annexure-IV
	Total	84	7277	2289.71	

3. Government after careful examination of the matter, hereby accord administrative sanction for an amount of Rs.22,89,71,000/- (Rupees Twenty two crores eighty nine lakhs and seventy One thousand only) towards the comprehensive restoration of (84) tanks in Karimnagar, Adilabad, Warangal, Khammam under "Mission Kakatiya" subject to instructions issued in the reference 2nd read above. The statement showing the details of tanks proposed for restoration is annexed to this order.

(pto)

4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702 COL on MI MH-101 Surface Water GH-11 Normal State Plan SH - (21) - Construction & Restoration of MI Sources - 530 Major Works - 531 Other Expenditure".

5. The Chief Engineer, Minor Irrigation (GB) shall take necessary action accordingly and to complete the work within the stipulated period without fail and furnish utilization certificate to Government for the amount sanctioned in Para (3) above.

6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O.No.1226/37/A2/EBS.IX/2015, Dated: 05-02-2015.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

S.K. JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

To

The Chief Engineer, Minor Irrigation (GB), Hyderabad

Copy to:-

The Dist. Collector, Karimnagar.

The Dist. Collector, Adilabad.

The Dist. Collector, Warangal.

The Dist. Collector, Khammam.

The Finance (EBS.IX) Department.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

PS to Hon'ble Minister (I. M, M&G and L A)

PS to Principal Secretary to Government, I & CAD Department.

PA to Dy. Secretary to Government (T), I & CAD Department

The I & CAD (MI.G) Department.

SF/SCs (C.No.5845/MI.T-A2/2015).

// forwarded by order //

SECTION OFFICER

Annexure-I
Statement showing the details of tanks proposed for restoration under Mission Kakatiya
Karimnagar District List - IV

Sno	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Estimate Cost		
									Cost for Repairs Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total cost Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
1	030294300901101	Peddacheruvu	Mustabad	Mustabad	Siricilla	78°-42'-59"	18°-16'-48"	361	30.98	17.79	48.77
2	030294301101302	Kothacheruvu	Chippalapally	Mustabad	Siricilla	78°-39'-39"	18°-17'-12"	98	11.18	4.82	16
3	030294301201102	Chinthal	Cheekodu	Mustabad	Siricilla	78°-41'-25"	18°-19'-33"	156	26.95	12.86	39.81
4	030294400703101	MedipallyCheruvu	Gopalraopally	Sircilla	Siricilla	78°-51'-15"	18°-22'-26"	136	22.22	2.39	24.61
5	030294401101301	Nallacheruvu	KasbeKatkur	Sircilla	Siricilla	78°-45'-20"	18°-45'-20"	57.77	16.47	2.9	19.37
6	030294400301302	Jangamvanikunta	Bonala	Sircilla	Siricilla	78°-46'-22"	18°-23'-49"	32.38	10.57	2.54	13.11
7	030294400805302	GopalaCheruvu	Ankusapur	Sircilla	Siricilla	78°-51'-15"	18°-22'-26"	61.53	15.76	4.02	19.78
8	030294100101301	Ramalakshmanlakunta	Vanpally	Yellareddipet	Siricilla	78°-34'-58"	18°-32'-12"	92	42.19	1.91	44.1
9	030294100201301	KothaCheruvu	Garjanapally	Yellareddipet	Siricilla	78°-36'-08"	18°-32'-15"	39.54	5.26	3.13	8.39
10	030294200301101	LingamCheruvu	Samudralingapur	Gambhirao pet	Sircilla	78°-35'-00"	18°-22'-30"	145	41.44	27.58	69.02

11	030294201001102	VenkatadriCheruvu	Gambhiraope t	Gambhirao pet	Sircilla	78°-34'-08"	18°-18'-00"	201	24.47	20.68	45.15
12	030294201001301	MangammaCheruvu	Gambhiraope t	Gambhirao pet	Sircilla	78°-33'-00"	18°-18'-00"	173.07	21.63	21.52	43.15
13	030294201001101	NamazCheruvu	Gambhiraope t	Gambhirao pet	Sircilla	78°-34'-16"	18°-19'-00"	373.31	19.74	18.06	37.8
14	030304602001301	GollaKunta	Gagillapur	Bejjanki	Manakon dur	79°-03'-00"	18°-04'-00"	52	12.31	17	29.31
15	030304602001305	ThummalaKunta	Gagillapur	Bejjanki	Manakon dur	79°-04'-00"	18°-13'-00"	68	6.77	22.28	29.05
16	030304601901301	Dayyalakunta	Dacharam	Bejjanki	Manakon dur	79°-03'-00"	18°-14'-00"	45	9.32	20.53	29.85
17	030304700201313	SingariKunta	Thimmapur	Thimmapur	Manakon dur	79°-11'-30"	18°-22'-10"	30	8.11	7.19	15.3
18	030304801301306	ChinthaKunta	Metpally	Shankarapa tnam	Manakon dur	79°-21'-29"	18°-17'-34"	23.03	12.21	4.14	16.35
19	030303500701101	OoraCheruvu	Killeda	Manakoun duru	Manakon dur	79°-17'-10"	18°-23'-50"	106	20.56	22.84	43.4
20	030304801001302	YapalaKunta	Vankayagude m	Shankarapa tnam	Manakon dur	79°-18'-00"	18°-18'-07"	34.3	10.4	4.45	14.85
21	030304502001302	KosaniKunta	Anantharam	Ellanthaku nta	Manakon dur	78°-54'-00"	18°-17'-50"	65	3.15	0	3.15
22	030304502001305	ThummalaKunta	Thippapur	Ellanthaku nta	Manakon dur	78°-58'-00"	18°-17'-50"	45	4.0	0	4.0
23	030304502001301	KasamKunta	Thippapur	Ellanthaku nta	Manakon dur	78°-57'-00"	18°-18'-00"	65	8.55	0	8.55
24	030241101301302	OoraCheruvu	Metpalli	Mahadevpur	Manthani	79°-55'-42"	18°-46'-42"	50.00	21.39	14.23	35.62

25	030284001801301	Errakunta	Dharmaram	Konaraopet	Vemulawada	78°-44'-41"	18°-26'-25"	22.55	2.95	3.40	6.35
26	030284000201302	Ranganicheruvu	Vattimalla	Konaraopet	Vemulawada	78°-39'-00"	18°-32'-30"	20.63	11.92	3.63	15.55
27	030241002902502	Kodesalakunta	Dastugiripalli (H/O) Ankushapur	Kataram	Manthani	79°-57'-11"	18°-38'-42"	80.00	30.72	15.88	46.60
								2633			726.99

S.K. JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

// forwarded by order //

SECTION OFFICER

Annexure-II
Statement showing the details of tanks proposed for restoration under" Mission Kakatiya"
Adilabad District List-IV

Sno	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Estimate Cost		
									Cost for Repairs Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total cost Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
1	010050603901301	Small tank	Narnoor	Narnoor	Asifabad	78-50'-22"	19-30'-25"	30	15.96	6.34	22.30
2	010052901801301	Small tank	Mahagaon	Narnoor	Asifabad	78-49'0.73"	19-29'21.94"	35	11.02	2.04	13.06
3	010050603801301	Small Kunta	Bheempoor	Narnoor	Asifabad	78-52'46.54"	19-30'28.65"	40	10.20	3.2	13.40
4	010054001801302	OoraCheruvu	Pulikunta	Rebbena	Asifabad	79°25'15"	19°13'	50	20.38	2.02	22.40
5	010054002101101	Konda Baba Cheruvu	Narayanapur	Rebbena	Asifabad	79°29'53"	19°14'16"	114	19.18	10.22	29.40
6	010054001901306	FakkeerpallyCheruvu	Nambala	Rebbena	Asifabad	79°27'19"	19°14'14"	54	19.45	4.60	24.05
7	010062603901301	ThetteKunta	Beersaipet	utnoor	Khanapur	78°49'20.03"	19°17'37.5"	60	7.99	1.40	9.39
8	010034900101301	OoraCheruvu	Buyyaram	Vemanapally	Bellampally	19 08 09	79 42 28	45	28.44	4.32	32.76
9	010034901501302	OoraCheruvu	Dasnapur	Vemanapally	Bellampally	19 05 12	79 49 47	60	1.73	14.43	16.16
10	010034901701301	Venkatammakunta	Vemanpally GP	Vemanapally	Bellampally	19 06 12	79 50 32	60	5.72	4.81	10.53
11	010080800501101	Peddacheruvu	Thosham	Gudihathnur	Boath	78°-57'-22"	19°-53'- 07"	167.00	1.99	21.61	23.60
12	010080900201301	New tank(KothaCheruvu)	Gubba	Ichoda	Boath	78°-45'-18"	19°-46'-27"	67	1.15	7.76	8.91
13	010080904001301	Dumpalacheruvu	Sirchelma	Ichoda	Boath	78°-53'-22"	19°-32'-76"	85	1.32	10.33	11.65

14	010025201301303	DavudaKunta	Mudigunta	Jaipur	Chennur	79 33 53	18 51 44	50	23.03	5.17	28.20
15	010025200602101	NawabKunta	Narsingapur	Jaipur	Chennur	79 36 28	18 48 03	400	4.12	7.58	11.70
16	010043201101301	Kodiselakunta	Uthkur	Luxettipet	Mancheria	79°12'59"	18°56'16"	20	9.09	2.31	11.40
17	010014601901301	Ooracheruvu	Thalodi	Kowtala	Sirpur	79° 44' 20.0"	19° 30' 31.0"	120	3.49	5.31	8.80
18	010014600501301	OoracheruvuThatipally	Thatipally	Kowtala	Sirpur	79° 42' 30.0"	19° 34' 10.0"	60	13.15	6.75	19.90
19	010014600601302	Chinnamadugucheruvu	MogadDagad	Kowtala	Sirpur	79° 43' 20"	19° 33' 45"	50	9.29	4.80	14.09
20	010014600601101	Chinthalacheruvu	mogaddagad	Kowtala	Sirpur	79° 44' 08.2"	19° 32' 46.2"	140	10.55	15.55	26.10
21	010014501201301	Bheemanakunta	sirpur	sirpur	sirpur	79° 34' 27"	19° 29' 02"	60	20.17	3.03	23.20
22	010080800701201	AmruthaDhara	Gudihathnur	Gudihathnur	Boath	78° 30' 42.49"	19° 31' 50.31"	150	1.14	6.51	7.65
Total								1886			388.65

S.K. JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

// forwarded by order //

SECTION OFFICER

Annexure-III
Statement showing the details of tanks proposed for restoration under "Mission Kakatiya"
Warangal District - List - 4

Sno	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Estimate Cost		
									Cost for Repairs Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total cost Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
1	091084001501303	Thurgulakunta	Sulthanpur	Regonda	Bhoopalpally	79°-48'-25"	18°-12'-22"	54	31.83	4.77	36.60
2	091084001101312	Dameracheroo	Kanaparthi	Regonda	Bhoopalpally	79°-42'-32"	18°-15'-07"	65	27.52	14.98	42.50
3	091094903501305	MukkidiPochammaCheruvu	Ilapuram	Eturnagaram	Mulugu	80°-15'06"E	18°-26'54"N	45	25.87	6.23	32.10
4	091094900601301	Gorrebondakunta	GuttalaGangaram	Eturunagaram	Mulugu	80°-20'-26"	18°-35'-19"	50	21.20	10.80	32.00
5	091094900201302	Madigonidoyyakunta	Bhupathipuram	Eturunagaram	Mulugu	80°-16'-52"	18°-33'-34"	61	31.76	10.34	42.10
6	091094902001302	Dombarucheru	Sarvai	Eturunagaram	Mulugu	80°-15'-25"	18°-31'-55"	85	27.73	8.97	36.70
7	091092802001301	Gilledukunta	Neelampally	Kothaguda	Mulugu	82°-05'28.56"	17°58'01.69"	70	24.28	4.62	28.90
8	091092801201314	Chakravarthulakunta	Otai	Kothaguda	Mulugu	80°-03'06.02"	18°00'16.25"	30	20.28	0.00	20.28
9	091092805601302	Errakunta	Kistapur	Kothaguda	Mulugu	80°-04'30.07"	17°52'46.66"	30	20.17	0.00	20.17
10	091092802801308	Ippalakunta	Pegadapally	Kothaguda	Mulugu	83°-05'28.56"	17°56'20.33"	50	34.02	0.00	34.02
11	091092802301303	Ippalakunta	Govindapur	Kothaguda	Mulugu	80°-04'17.00"	17°57'54.35"	35	21.18	0.00	21.18

12	091092802801312	Perukavarikunta	Pegadapally	Kothaguda	Mulugu	80 04'04.41"	17°56'48.80"	40	25.32	0.00	25.32
13	091094600109306	Dameracheruvu	Gurrampet	Venkatapur	Mulugu	79°-56'-18"	18°-21'-36'	40	16.22	11.31	27.53
14	091094600109305	Bachanicheruvu	Gurrampet	Venkatapur	Mulugu	79°-56'-18"	18°-21'-36'	35	16.66	9.77	26.43
15	091094600805305	Buchikunta (PR)	Keshavapur	Venkatapur	Mulugu	79°-54'-15"	18°-16'-15'	20	8.19	4.26	12.45
16	091094600601301	Ganesh kunta	Nallakunta	Venkatapur	Mulugu	79°-58'-15"	18°-17'-30"	22	11.70	4.10	15.80
17	091094600804301	Sigarikunta	Narsapur	Venkatapur	Mulugu	79°-54'-06"	18°-14'-00"	15	7.43	3.37	10.80
18	091094700501301	Kothakunta	Rangapur	Govindaraopet	Mulugu	80-9-56	18-09-48.	50	15.04	6.11	21.15
19	091032600801304	Thummalakunta	Redlawada	Nekkonda	Narsampet	79-50-50.	18-02-35.	75	18.95	22.40	41.35
20	091032600401101	Ooracheruvu	Panikara	Nekkonda	Narsampet	79-49-24.	18-03-15.	200	22.68	19.17	41.85
21	091032601301101	Peddacheruvu	Venkatapur	Nekkonda	Narsampet	79-53-26.	18-04-30.	200	29.14	30.96	60.10
22	091043100901101	Peddacheruvu	Oorugonda	Athmakur	Parkal	79°-41'-23"	18°-03'-57"	212	76.65	58.24	134.89
23	091071000301101	Peddacheruvu	Yellapur	Hasanparthy	Wardhannapet	79°-29'-25"	18°-04'-44"	536.3	48.15	33.60	81.75
Total								2,020			845.97

S.K. JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

// forwarded by order //

SECTION OFFICER

Annexure-IV
Statement showing the details of tanks proposed for restoration under" Mission Kakatiya"
Khammam District List-IV

Sno	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Estimate Cost		
									Cost for Repairs Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total cost Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
1	101144500101101	BuchireddypalemCheru	Rompimalla	Madhira	Madhira	80-22-00	17-01-00	160	28.90	37.90	66.80
2	101144600901301	Ooracheru	Shakenaveedu	Yerrupalem	Madhira	80-28-00	16-54-00	50	8.85	17.35	26.20
3	101144601001301	Ooracheru	Thakkalapadu	Yerrupalem	Madhira	80-27-25	16-52-30	68	10.75	19.65	30.40
4	101123600301301	YerraCheru	Manchukonda	Khammam Urban	Khammam	80-13-33	17-21-11	89	20.85	38.15	59.00
5	101152000901303	VarvaKunta	Manikyaram	Singareni	Wyra	80-20-35	17-28-26	47	11.41	10.19	21.60
6	101123600503304	RegulaKunta	Mallepalli	Khammam Urban	Khammam	80-13-45	17-19-21	35	8.24	9.86	18.10
7	101133801301302	ReddiKunta	Bachodu	Thirumalayapalem	Palair	79-54-18	17-18-37	80	13.57	20.53	34.10
8	101111800301303	JogaAbbaiahKunta	Gangaram	Tekulapally	Yellandu	80-32-31.48	17-39-4.36	30	10.24	1.26	11.50
9	101112300201302	Narsaiah Dora Kunta	PathaLingala	Kamepally	Yellandu	80-14-50	17-23-40	20	8.04	0.36	8.40
10	101112300407303	BuchayaKunta	Thallagudem	Kamepally	Yellandu	80-15-40	17-27-15	70	13.15	4.75	17.90
11	101112300202301	YeddulaKunta	KothaLingala	Kamepally	Yellandu	80-14-30	17-24-45	40	10.79	6.11	16.90

12	101112301101304	KistarayuduKunta	Komminipally	Kamepally	Yellandu	80-13-13	17-22-35	49	12.93	4.27	17.20
Total								738			328.10

S.K. JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

// forwarded by order //

SECTION OFFICER

